
Subject: How did this occur?

Posted by [timeliz](#) on Tue, 25 Apr 2017 18:24:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

This was an interesting find upon opening my newest 833 model:

Did this happen intentionally or unintentionally at the factory; or was it a repairman's substitution?
The ratchet wheel isn't normally a part that needs replacing. Very interesting.
