Subject: Re: How did this occur?
Posted by timeliz on Tue, 25 Apr 2017 19:59:53 GMT
View Forum Message <> Reply to Message

I did have the thought that this could be the backside.
Now I'll have to go check out a couple other 833's....

Update: I checked the back of the ratchet wheel of 2 spare 833s and they are blank. Curious.

... just checked a third with serial number closer to the posted movement and its blank also.