Subject: Re: Fully restored all-Swiss watch with 24-hour dial
Posted by MonKee on Thu, 21 Jan 2016 17:32:10 GMT
View Forum Message <> Reply to Message

I wish I knew more about Metallurgy but I am beyond ignorant on the subject. Given this I have to ask that since the majority of these that were not marked Pan Am were Stainless Steel cases and the ones marked Pan Am were some metal that was then plated is it possible the the shrinkage factor between the two would cause the need for this thread adjustment?