
Subject: Re: Caliber 641 (640) - Factory R Gruen Guild
Posted by [Barney Green](#) on Mon, 24 Aug 2020 07:33:47 GMT
[View Forum Message](#) <> [Reply to Message](#)

The differing setting bit looks like a replacement to me, may be the spring was broken like from your second example and the replacement part looks different? Other than that the movement looks the same to me.
