

---

Subject: Re: The Caliber UltraThin

Posted by [thesnark17](#) on Sat, 30 Apr 2022 20:13:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

True, that.

Unfortunately, with the thickness of the movement plates, it may be impossible to repair the threads if they are bad. I assume that they were stripped, necessitating the epoxy; I suppose it's possible that it's the wrong screw and too small for the hole but it seems unlikely.

---