

---

Subject: Re: The Caliber UltraThin

Posted by [JackW](#) on Sun, 01 May 2022 00:07:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

thesnark17 wrote on Sat, 30 April 2022 14:13 True, that.

Unfortunately, with the thickness of the movement plates, it may be impossible to repair the threads if they are bad. I assume that they were stripped, necessitating the epoxy; I suppose it's possible that it's the wrong screw and too small for the hole but it seems unlikely.

I'd kindly disagree, that it is impossible. Just freaking difficult. Like doing a helicoil on an engine block. Except smaller. Granted, this is arm-chair quarterbacking at its finest.

---