

---

Subject: Re: How did this occur?

Posted by [timeliz](#) on Tue, 25 Apr 2017 19:59:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I did have the thought that this could be the backside.

Now I'll have to go check out a couple other 833's....

-----

Update: I checked the back of the ratchet wheel of 2 spare 833s and they are blank. Curious.

... just checked a third with serial number closer to the posted movement and its blank also.

---