

---

Subject: Re: How did this occur?

Posted by [Thojil](#) on Sun, 30 Apr 2017 20:07:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

timeliz wrote on Tue, 25 April 2017 20:24

Did this happen intentionally or unintentionally at the factory; or was it a repairman's substitution?

The ratchet wheel isn't normally a part that needs replacing. Very interesting.

Unintentionally at the factory I would guess highly unlikely as it would have never passed through quality control from my perspective.

More likely a repairman's substitute. This happened(s) frequently with Gruen 877 and the Rolex 300 calibers I heard, where Gruen 877 movements are used for donor parts to restore a Rolex Prince which has a 3-4 times higher value than a Gruen Techni Quadron

---