

---

Subject: Re: CAL 311

Posted by [JackW](#) on Sun, 08 Oct 2017 15:27:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Quote:and see if I missed something

The 311 is twitchy... double and triple check in the leaves of the pinions on all of the wheels.

Check your escape wheel tool; might have worn teeth. Also check to see if the pallet is rubbing on the roller. For this you might need to just have the balance and pallet fork in place to really see into it. Do you have a timing machine? That could help pin point whats going on in the train for the short period you can get it to run.

Cheers!

---