
Subject: Re: Semithin 754/756/758

Posted by [Jenneke](#) on Sun, 02 Jan 2022 19:10:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

Something fishy is going on.

Caliber 758 exists with 15 and 16 jewels.

In the 1939 material catalogue the 754, 756 and 758 have the same setting mechanism:

The spare 754 movement I bought for my 756 turns out to have a different setting mechanism.

In fact, that looks the same as the caliber 740 in the 1926 parts catalogue. Almost as if the 740 is the 17 jewel and the 754 the 15 jewel version.

Somewhere over the years the 754 setting bits where changed. From a two part stem to a single, from two sides setting bits to one side with different shapes.

File Attachments

1) [58D8E168-C0BB-4DDF-A791-161FEBFEE6CE.jpeg](#), downloaded 2538 times

17'''

No. 754-756-758



No. 754 — 15 jewels } (*straight escape*
No. 758 — 15 jewels } *wheel pivots*)
No. 756 — 17 jewels (*has center wheel*
jeweled)

2) [604937BE-337C-43FF-8044-97925CD7D033.jpeg](#), downloaded 2471 times



3) [A3E2E698-2687-4027-B207-1127A23F2F96.jpeg](#), downloaded 2434 times



4) [A7F20DEB-DC7B-4BB2-B8EC-9870CFDD2591.jpeg](#), downloaded 2452 times

