

---

Subject: Re: ###

Posted by [koskid](#) on Fri, 06 Jun 2014 15:39:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks,

Yes there is a chrome reflector ring between the crystal and the case.

I may try to polish out the crystal rather than replace. I had great success doing that with a couple other watches with badly scratched crystals.

Measuring the gasket seat in the case it looks like about 28.5mm ID and 30.5mm OD. Maybe I'll get a couple about this size and see what fits best. I'm pretty close to Otto Frei so maybe I'll run over there today.

---