

---

Subject: Re: Moisture Proof Military Model

Posted by [afire](#) on Wed, 08 Jul 2015 15:38:09 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thojil wrote on Thu, 02 July 2015 16:51 The only thing that is broken is the connecting link between the inner watch case and outer protection case. I will have a look at that when it arrives. That should be no problem at all for a competent goldsmith to fix. It's really nothing more than a simple bent rod forming a hook. I had one of these years ago, but the pictures I still have aren't very good and only one give some hint of what the hook looks like, but a picture of the inner case outside the outer case would have been more helpful.

But the case serial number on mine was 568475.

---