

---

Subject: Re: Gruen Ladies Watch

Posted by [afire](#) on Mon, 22 Jul 2019 14:28:52 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

These cabachon crowns were very commonly used for replacements, and crowns are a part that fairly routinely needs replacing. I don't see any reason to suspect that it came from the other watch. Very handsome watch. You see "C" instead of "K" for karat every now and then. I have no idea what the rhyme or reason is, but suspect that there must be one.

---